



AIRCRAFT ENGINES

SERVICE BULLETIN

CHANGE OF COOLANT SPECIFICATION ON ROTAX® ENGINE TYPE 912 AND 914 (SERIES)

SB-912-043 UL

SB-914-029 UL

MANDATORY

Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

1) Planning information

1.1) Engines affected

All versions of the engine type:

- 912UL all
- 912ULS all
- 912ULSFR all
- 914UL all

For complete instructions and compliance to this service bulletin refer to Service Bulletin SB-912-043/SB-914-029, latest edition section 1.2 onward.

- ◆ **NOTE:** Section 1.6) Approval: Is not required for engines of the type UL (series).
Section 3) Accomplishment: In addition: persons with adequate type-specific training.

d03374