

# SERVICE BULLETIN

## USE OF AN ADAPTED PROPELLER GOVERNOR ON ROTAX® ENGINE

### || TYPE 912 A3 AND 912 F3

### SB-912-011

## OPTIONAL

### Repeating symbols:

Please, pay attention to the following symbols throughout the Service Bulletin emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **ATTENTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

### Subject

Use of the propeller governor Woodward A 210790.

### Engines affected

- || All engines of the **Type 912 A3 and 912 F3** which are planned for operation with a hydraulically controlled feathered pitch propeller.

### Reason

The use of a propeller with a hydraulic controlled feathered pitch requires a prop governor to induce and store pressure for pitch reduction.

### Compliance

At request of customer for conversion for a propeller as stated above.

### Remedy

Exchange or installation of the prop governor Woodward A 210790 according to Maintenance Manual for Rotax 912 A, chapter 14.4.8 and 14.4.9.

### Accomplishment

The necessary measures have to be taken and confirmed by the engine producer or by entitled persons from the Aviation Authorities.

### Approval

- || The technical content of this Service Bulletin has been approved by ACG.